Risk Assessment – Record of significant findings					
Risk assessment for		Assessment undertaken			
Building	Gwylan House	Date:	2009		
	Wesley Square	Reviewed:	2014		
	Mousehole	Completed by:	J L L Underhill		
	TR19 6RU	Signature:			
Floor/area:	Two storey cottage	Use: Self catering accommodation			
	Four bedrooms				
	Maximum five guests				

Step 1 – Fire hazards

Sources of ignition	Sources of fuel	Sources of oxygen
Heat from cooking	Cooking oils, toaster	
Electrical fault	Surrounding materials	
Tumble dryer	Clothes in utility room	
Smoking materials	Furniture and bedding	
Candles	Surrounding materials	

Step 2 – People at risk

April 2014

Guests anywhere in the house, including children.

The property is not recommended for children under 5 and guests with mobility difficulties

Step 3 – Evaluate, remove, reduce and protect from risk

Review date	Completed by	Signature	
Assessment review	Completed by	Oi ma a tuma	
	 Emergency lighting power fails. 	in bedrooms, hall and landing if	
	Escape ladder in rear bedroom.		
	Exit route signed, keys to exit doors attached to doors.		
	and giving guidanc	e of what to do in case of fire	
people from a fire	Information cards in	n each bedroom giving escape route	
and reduce the risk to	with instructions for	• •	
Action taken to remove	 Fire extinguisher ar 	nd fire blanket supplied in kitchen	
	batteries fitted in ha	allway and upstairs lending	
that may cause a fire	 Interlinked mains o 	perated smoke alarms with 10 year	
and reduce the hazards	Electrical appliances are regularly inspected		
Action taken to remove	Electrical installation	on is regularly inspected	
Who is at risk?	Everyone in the ho	use, by day or night	
	 Smoking not permi 	tted, candles not supplied to guests	
	risk, guests to exer	cise normal care.	
What is the risk?	 Cooking, laundry ri 	sk no greater than normal domestic	

J L L Underhill